

Cub Cadet

Power Equipment

SERVICE BULLETIN

CODE NO: CC-189

DATE: JANUARY 19, 1990

SUBJECT: CARE OF PLASTIC COMPONENTS ON 1990 GARDEN TRACTORS

THE PLASTIC COMPONENTS (GRILLE, HOOD & SIDE PANELS) ON YOUR 1990 GARDEN TRACTOR REQUIRE SPECIAL CARE IN CLEANING AND POLISHING. THESE PARTS ARE MADE MANUFACTURED FROM "XENOY", A ENGINEERED MATERIAL FROM GENERAL ELECTRIC.

FROM THE EXPERIENCE GAINED FROM USING XENOY IN THE AUTOMOTIVE INDUSTRY, WE HAVE FOUND THE BEST SYSTEM TO BE:

STEP 1. CLEAN XENOY WITH ARMOR-ALL CLEANER.

STEP 2. POLISH XENOY WITH ARMOR-ALL POLISH.

BY FOLLOWING THIS PROCEDURE, THE PART WILL BE BROUGHT BACK TO ITS ORIGINAL GLOSS LEVEL.

WIPING XENOY PARTS WITH ANY SOLVENT WILL IMMEDIATELY DULL THE FINISH AND YOU MAY NOT BE ABLE TO RESTORE THE ORIGINAL GLOSS LEVEL.

CAUTION: WHEN CARRYING A TRACTOR ON AN OPEN BED TRUCK YOU MUST SECURE THE HOOD. THE WIND CAN COME IN THROUGH THE HEAT DUCTS AND OPEN THE HOOD CAUSING DAMAGE TO THE PARTS AND HINGE. A TIE DOWN STRAP IS RECOMMENDED DURING TRANSPORTATION.

